





Root Elevators






Root Elevators





Root Elevators



786-269
Fig.A
Cogswell



786-270
Fig.B
Cogswell



786-271
Fig.301
Apexo



786-272
Fig.302
Apexo



786-273
Fig.303
Apexo



786-274
Fig.301W
Seldin



786-275
Fig.304W
Seldin



786-276
Fig.1H
Heidbrink



786-277
Fig.2H
Heidbrink



786-278
Fig.40H
Heidbrink



786-279
Fig.41H
Heidbrink




786-280
Fig.46



786-281
Fig.46R




Root Elevators





Root Elevators



786-298
Fig.A2C
Coupland

786-299
Fig.A3C
Coupland

786-300
Fig.15
Woodward

786-301
Fig.16
Woodward

786-302
Fig.1C
Coupland

786-303
Fig.2C
Coupland

786-304
Fig.3C
Coupland

786-297
Fig.A1C
Coupland

786-305
Fig.11M
Mac Millan

786-306
Fig.12M
Mac Millan

786-307
Fig.13M
Mac Millan

786-308
Fig.8
Crane

786-309
Fig.21
University of Michigan


786-310
Fig.69W
Woodward

786-311
Fig.31F
Friedman

786-312
Fig.32F
Friedman



Root Elevators



786-313
Fig.1
Bein



786-314
Fig.2
Bein



786-315
Fig.3
Bein



786-316
Fig.4
Bein




786-317
Fig.5
Bein



786-318
Fig.6
Bein



786-319
Fig.1



786-320
Fig.2



786-321
Fig.2
Flohr



786-322
Fig.3
Flohr



786-323
Fig.7
Cryer



786-324
Fig.8
Cryer



Root Elevators



786-325
Fig.1
Heidbrink




786-326
Walter F. Barry



786-331
Fig.2
Heidbrink



786-332
Fig.3
Heidbrink



786-333
Winter



786-334
Fig.11LW



786-335
Fig.11RW



786-336
Fig.12LW



786-337
Fig.12RW



786-327
Fig.320



786-328
Fig.321




786-329
Fig.322



786-330
Fig.323

Walter F. Barry



786-339
Fig.2
Warwick-James



786-340
Fig.3
Warwick-James

786-338
Fig.1
Warwick-James